

b opk

**FITNESS CERTIFICATE**  
**TO BE FILLED BY THE INSPECTING OFFICER**  
( Assistant Engineer / Assistant Executive Engineer )  
( Re:G.O Ms 20/70/PWD Dt 23-01-1970 )

1 Name of School/Institution : The Green Hills Public School, Moolankave  
L.S.G.D. Section Noolpuzha Grama Panchayath  
2 Name of the Officer : Vineetha.C.T  
Assistant Engineer, Noolpuzha Grama Panchayath

3 Location with name of Education : S Bathery  
District / sub.district wayanad  
4 Period from which the certificate is issued : 2023-24

5 Types of building : **RCC BUILDING -1**  
GF 6.23x9.63x3.60 - Office room  
6.23x13.69x3.60 - class room  
6.23x6.23x3.60 - 5 Office room  
6.23x6.23x3.60 - Visitors room  
6.23x6.10x3.60 - Principal room  
6.23x6.10x3.60 - Visitors room  
3.00x6.10x3.60 - Staff room  
8.00x8.13x3.60 - Center hall  
FF 6.23x6.10x3.60 - 8 class room  
6.23x11.60x3.60 - class room  
6.23x9.63x3.60 - class room  
8.00x7.11x3.60 - Conference hall  
3.00x6.10x3.60 - Staff room  
SF 6.23x6.10x3.60 - 8 class room  
6.23x6.10x3.60 - class room  
6.23x10.86x3.60 - class room  
8.00x13.44x3.60 - class room

**RCC BUILDING-2**

CF 6.28X6.27X3.60- 3 Classroom  
GF 3.10X6.50X3.60 - Store room  
15.90X6.50X3.60 - lab rooms  
10.50X6.50X3.60 - lab rooms  
11.95X6.50X3.60 - lab rooms  
6.28X6.50X3.60- 2 Classroom  
6.00X6.70X3.60- 3 Classroom  
FF 6.20X6.50X3.60 -7 Classroom  
6.20X6.50X3.60- Staff room  
3.60X6.50X3.60- Office room  
SF 6.20X6.50X3.60 - 7 Classroom  
6.20X6.50X3.60 - Staff room  
3.60X6.50X3.60 -Office room

**TERRACE FLOOR**

16.93X6.50- Dormitory  
16.93x1.80 -Verandah  
3.80x3.95x3.60 -Office

6 Nature of defect any  
a).Foundation and basement : nil  
b).Superstructure : nil  
c).Doors and Windows : nil  
d).Wood work wrought and put up : nil  
e).Roof : nil  
f).Flooring : nil  
g).Miscellaneous (Cracks if any ) : nil

For The Greenhills Public School

  
Chairman



  
**Dr. C J CHACKO, PRINCIPAL**  
KL-75433, THE GREENHILLS PUBLIC SCHOOL  
SULTHAN BATHERY, MOOLANKAVE P.O..  
WAYANAD DT. - 673 592

- 7 Any major defect noticed which will render the building unsafe in any manner : nil
- 8 Whether maintenance work have been done properly : yes
- 9 Whether the structure is sound or not for conducting classes : **Structure is sound under normal climatic condition**


Note: 1.The Stability of structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.

2.Any additional observation deemed necessary for the Certificate, may be furnished separately with the Certificate

**CERTIFICATE**

**Certified that the School building was inspected by me on ...30/05/2023.. and found to be fit / unfit to conduct classes for the period 2023-24 for the reasons stated above**

Place : Naiketty  
Date : 30/05/2023


Signature   
Asst: Engineer  
ASSISTANT ENGINEER  
L. S. G. D. SECTION  
MOOLPUZHA GRAMA PANCHAYATH  
NAIKETTY



**For The Greenhills Public School**

  
Chairman



  
**Dr. C J CHACKO, PRINCIPAL**  
KL-75433, THE GREENHILLS PUBLIC SCHOOL  
SULTHAN BATHERY, MOOLANKAVE P.O.  
WAYANAD DT. - 673 592